


# RFC3849 and RFC5737

Documentation! Documentation! Documentation!



# Documentation matters


# Why?



Network / NET-16171

sw02.evr03 spitting errors

# Flipperty Flopperty



# Nothing is straightforward

[REDACTED] added a comment - 18/Sep/19 10:15 AM - [edited](#)

so I think what's happening is that the Nexus receive a broken frame, because of cut-through the frames is forwarded to the dest [REDACTED] with a bad CRC on purpose (stomping on the Nexus)

```
[REDACTED]$ /sbin/ifconfig ext0 | grep err
RX errors 1746054969 dropped 195799 overruns 0 frame 1746054969
TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
[REDACTED]$ /sbin/ifconfig ext0 | grep err
RX errors 1746064939 dropped 195799 overruns 0 frame 1746064939
TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
[REDACTED]$ /sbin/ifconfig ext0 | grep err
RX errors 1746076243 dropped 195799 overruns 0 frame 1746076243
TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
```

BUT for some reason the Nexus won't tell us where the broken frames are coming from (no CRC counter increasing)

so imho the issue here is a display issue more than a switch behavior


I'm pretty sure the problematic traffic comes from the same ToR since we would see CRC on the core01.ewr03 as well.

# TCPDump!

[REDACTED] added a comment - 01/Nov/19 11:47 AM

I enabled 'rx-fcs' on ext0 and did a ethernet capture with tcpdump:

## TCPDump! (contd.)



## Combined problems == hard problems



[REDACTED] admin

Tom Strickx


Yup, but odd that the QFXs didn't spot it

nexus has a long feature of reading deeper into packets than it should. had similar issues in [REDACTED]  
with the N7K

## Documentation?

?

## And the penny drops



# Documentation Matters!

<https://www.cisco.com/c/en/us/products/collateral/switches/nexus-5000-series-switches/white-paper-c11-733110.pdf>

You next need to define the source for the ERSPAN session: an interface, VLAN, or VSAN from which traffic will be mirrored. By default, traffic is monitored in both directions if the source is a port or PortChannel. To monitor traffic in only one direction, you must specify the transmit (tx) or receive (rx) parameter. To define a port and a PortChannel as the source of the ERSPAN session, use these commands:

```
switch(config-erspan-src)# source interface ethernet 1/1 [tx|rx|both]
switch(config-erspan-src)# source interface port-channel 101 [tx|rx|both]
```

To define a VLAN and a VSAN as the source of the ERSPAN session, use these commands:

```
switch(config-erspan-src)# source vlan 1
switch(config-erspan-src)# source vsan 1
```

The ERSPAN source session needs a defined destination IP address to which to forward traffic. The ERSPAN session can have only one destination IP address. Use the command to configure the destination IP address:

```
switch(config-erspan-src)# destination ip 1.1.1.1
```

Define the ERSPAN ID for the ERSPAN flow with this command:

```
switch(config-erspan-src)# erspan-id 1
```

To define a specific VRF to use instead of the global VRF, use either of these commands:

```
switch(config-erspan-src)# vrf default
```

or

```
switch(config-erspan-src)# vrf vrf-name
```

You can also define optional parameters: access control list (ACL), TTL, maximum transmission unit (MTU) for truncated ERSPAN, and differentiated services code point (DSCP) values.

In the source session, you can configure ACLs to filter packets in the ERSPAN session:

```
switch(config-erspan-src)# filter access-group erspan_acl filter
```

To limit the number of jumps from the source to the destination and stop traffic from going to an unvented device, you can define the IP TTL. To configure the IP TTL for packets in ERSPAN traffic, use this command:

```
switch(config-erspan-src)# ip ttl 1
```

To prioritize ERSPAN traffic over some less important production traffic, you can change the DSCP value. By default, ERSPAN traffic is assigned a DSCP value of 0. To define a different DSCP value for packets in ERSPAN traffic, use this command:

```
switch(config-erspan-src)# ip dscp 1
```

If ERSPAN traffic is oversubscribing a network link, you can reduce the load by defining an MTU value. The MTU value for truncated ERSPAN packets can be between 64 and 1518 bytes. Use this command:

```
switch(config-erspan-src)# mtu 64
```

switch(config-erspan-src) # destination ip 1.1.1.1

Welp

<https://blog.cloudflare.com/fixing-reachability-to-1-1-1-globally/>

# Announcing 1.1.1.1: the fastest, privacy-first consumer DNS service

01/04/2018




Matthew Prince

# Awkward

<https://twitter.com/Cloudflare/status/1316062417416327169>

Cloudflare  @Cloudflare

Argo Tunnels that live forever. [cfl.re/3dqjzN6](https://cfl.re/3dqjzN6)  
#ZeroTrustWeek




Argo Tunnels that live forever  
Securely connecting your infrastructure to Cloudflare's network just became easier.  
[blog.cloudflare.com](https://blog.cloudflare.com)

6:05 pm · 13 Oct 2020 · Sprout Social

19 Retweets 3 Quote Tweets 19 Likes

# Awkward

<https://twitter.com/Cloudflare/status/1316062417416327169>



# Awkward

<https://twitter.com/Cloudflare/status/1316062417416327169>



## Awkward

@  
Doing a little weekend coding.  
[#DevNet](#)


Checking certificates...  
v cert for vManage expires at 2025-05-19 02:01:37.  
There are 1626 days remaining.

| Host name   | System IP | Expiration date          | Validity |
|-------------|-----------|--------------------------|----------|
| vBond-East  | 1.1.1.2   | Oct 28 23:59:59 2022 GMT | valid    |
| vBond-West  | 1.1.1.3   | Oct 28 23:59:59 2022 GMT | valid    |
| vSmart-East | 1.1.1.4   | Oct 28 23:59:59 2022 GMT | valid    |
| vSmart-West | 1.1.1.5   | Oct 28 23:59:59 2022 GMT | valid    |
| vmanage     | 1.1.1.9   | Nov 27 08:09:00 2021 GMT | valid    |

7:23 am · 5 Dec 2020 · Twitter Web App

---

131 Likes



## RFC3849 and RFC5737

July 2004

**IPv6 Address Prefix Reserved for Documentation**

January 2010

**IPv4 Address Blocks Reserved for Documentation**

For those in the back

RFC3849

and

RFC5737

## Summary - RFC3849

2001:DB8::/32

## Summary - RFC5737

192.0.2.0/24

198.51.100.0/24

203.0.113.0/24

## Summary



# Thank you!



@tstrickx



tstrickx@cloudflare.com

